



PDX50 ACCESSORIES

Everything you need. Built for performance.
Designed to maximize productivity and
protect your PDX50 every step of the way.



ACC-5325
PDX50 / Spare Battery
Charger

PDX50 Single Slot Charging
Cradle, Spare Battery Charger



CAS-5300LD
PDX50 Handle Lanyard

Wrist Lanyard for PDX50 Handle



180-5300
PDX50 Spare Battery

PDX50 spare battery, 5000mAh



PWR-5V2A-USB
PDX50 Power Supply

5V/2A wall adapter for
fast and reliable charging.



ACC-5300-HND
PDX50 Handle

Snap On Handle For PDX50



CBL-USBC-USB A2-2M
PDX50 Charging Cable

6ft USB-C to USB-A cable
for charging and data
transfer.



CAS-5300HS
PDX50 Hand Strap

Adjustable Hand Strap for
PDX50



ACC-PDX50SP

6in Oleophobic screen protector.
shatterproof, shock-absorbing,
and scratch-resistant.